



NOTE: These assemblies tested Factory Mutual  
Design WP 621 and Factory Mutual WP 612

SHAFTWALL FIREMAN SWITCH AND INDICATOR BOX  
(SECTION A-A)